



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program

Date:

July 14, 2010

Reviewed: 

Mine Name: Levan Chicken Creek	Permit Number: M0230016
Operator Name: Sunroc Corp.	Inspection Date: 07/13/2010
Inspector(s): Wayne Western	Time: 11:40 AM - 12:50 PM
Other Participants: none	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

Both pits were inactive at the time of inspection. The west pit was unlocked. The east pit gate was lock. The site appears to be stable, no signs of erosion or slope failure.

The Permittee is actively mining in the east pit. They are working to get additional areas permitted.


The bond renewal date is January 21, 2007. The Permittee must update the bond.

Conclusions and Recommendations:

The Division should continue to monitor the site and follow up on the bond escalation.

Inspector's Signature

WHW



Inspection Date: July 13, 2010

Page 2 of 3

M/023/0016

CC: Sunroc - Tony Christofferson, Rod Dolph
Agency – Uinta NF- administered by Manti-LaSal NF

O:\M023-Juab\M0230016-Levan-chickencreek\draft\INSP_07152009.doc



Overview of west pit



Pit west area